


FIG.2A



F16. 2C	440
A B	442 T 446 -450 OUT
	At E

F16-2B

Å	В	В	Α+B
0	0	1.	·o.
1	0	1	1
0	1	∵0	1
1	7	۵	1
	<u> </u>		

F16. 2D

•			
A	8	3	ALE
٥	Ō	1	1
1	.0 0	1	1
٥	7	0	0
1	1	٥	1
	į į		